

Martin Guitar Repair


Here is a Martin Dreadnought that was severely abused by someone's unhappy girlfriend (not mine). It was kicked in and thrown across the room.



Rather extensive damage



Damaged Area Removed



Adding New Kerfing

I got a set of rosewood replacement sides from Martin in order to match the curve and wood type. The grain did not match all that well but as you can see the finished repair is barely visible. Due to the way I backed and re-enforced the patch, the repair is stronger than the original unbroken wood.



Extreme Guitar Repair